

Date: Thursday, 31/07/2008 9:23:12 AM  
 User: Melanie Fauteux

## Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: DISASSEMBLE
Job Number	: 40838		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D34463
This Issue	: 31/07/2008 S.O. No. :	Drawing Number	: D34463
Prsht Rev.	: NC	Project Number	:
First Issue	: 31/07/2008 Type : PURCHASED PARTS	Drawing Revision	:
Previous Run	: 00015	Material	:
Written By	:	Due Date	: 31/07/2008 Qty: 1 Um: Each
Checked & Approved By	: <u>mf 08-07-31</u>		
Comment	:		

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

PULL FROM STOCK: D3446-041 QTY X 1

REMOVE D3446-3 (MALE BUCKLE)

2.0	D3446041	Harness Assembly
-----	----------	------------------



(1x)

Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)  
 Harness Assembly

B# 402088/7/30SP

3.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



(1x)

Comment: PACKAGING RESOURCE #1

REPACKAGE ,IDENTIFY AND STOCK  
 D3446-3 WITH NEW BATCH #

LOCATION:

SEND REMAINING ITEMS TO QC

8/7/31

Date: Thursday, 31/07/2008 9:23:12 AM  
User: Melanie Fauteux

## Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: DISASSEMBLE

Job Number: 40838

Part Number: D34463

Job Number:



Seq. #:

Machine Or Operation:

Description :

4.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

S 08/07/31 (x)

5.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/07/31

Job Completion



MF 08-07-31